

Table 1: Priority Erosion Hazards across Brampton within TRCA jurisdictions

Priority	Sites ID	General Location	Deficient/At Risk
7	E22-ESA1 (Hazard)	Centennial Park	<ul style="list-style-type: none"> <li>• Unnamed Paved Trail (Dist. to hazard: 0.7m)</li> </ul>
6	WH-7-52 (EC asset) WH-7-58 (EC asset)	Carabram Park	<ul style="list-style-type: none"> <li>• West Humber Trail (Dist. to hazard: 0.8m)</li> </ul>
1	EMS926 (Hazard)	244 Pressed Brick Drive	<ul style="list-style-type: none"> <li>• Allan Kerbel Pond Berm</li> </ul>
2	TS4-01.11 (EC asset)	300 Orenda Drive	<ul style="list-style-type: none"> <li>• Birchbank Park Trail</li> </ul>
	TS4-01.12 (Hazard)		<ul style="list-style-type: none"> <li>• Concrete &amp; Gabion Channel</li> </ul>
	TS4-01.15 (EC asset)		<ul style="list-style-type: none"> <li>• 300 Orenda Drive Property</li> </ul>
3	E24-28 (EC asset)	Loafer's Lake Park	<ul style="list-style-type: none"> <li>• Lake Recreation Centre</li> </ul>
	E24-30 (Outfall)		<ul style="list-style-type: none"> <li>• SL-79349 Outfall (Dia.: 1.20m)</li> </ul>
	E24-32 (Outfall)		<ul style="list-style-type: none"> <li>• SL-128939 Outfall (Dia.: 0.45m)</li> </ul>
4	E24-48 (EC asset)	Sandalwood Park	<ul style="list-style-type: none"> <li>• SL-2406 Outfall (Dia.: 1.20m)</li> </ul>
	E24-49 (Outfall)		
		Loafer's Lake Park	<ul style="list-style-type: none"> <li>• Outfall OF_1321 (located southeast of Dawnridge Trail)</li> </ul>
		Evergreen	<ul style="list-style-type: none"> <li>• Rear Watercourse Dredging &amp; Restoration</li> </ul>
		Heath to Simpson	<ul style="list-style-type: none"> <li>• Watercourse Dredging &amp; Restoration</li> </ul>
		Brampton Transit to Simpson	<ul style="list-style-type: none"> <li>• Watercourse Dredging &amp; Restoration</li> </ul>
	WQU_28- OF_1622 WQU_100- OF_4125 WQU_11- OF_3770 WQU_12- OF_3768	City of Brampton	<ul style="list-style-type: none"> <li>• Various (4 sites) Outfall Remediation Projects</li> </ul>