



Brampton School Traffic Safety Council Site Inspection Report April 7, 2025 - Ward: 6

School/Location: St. Aidan Catholic School, 34 Buick Boulevard

Principal: Adrienne Dalli

Time(s): 7:50 a.m. and 2:50 p.m.

Phone: 905-840-3042

Weather: a.m. bright; p.m. overcast

Requested By: Rebecca Rosario

Nature of Problem: Pre-inspection prior to buses being removed for St. Adian School. In September students will be crossing Wanless Drive and Thornbush Boulevard and Wanless Drive and Brisdale Drive.

Observers Present: A.M. and P.M. Dominique Darmanin-Sturgeon, Member, Co-Chair; Don Harberer, Member A.M and P.M; Ana Carvalho, Coordinator, Crossing Guards, A.M and P.M; Kim Bernard, Coordinator, Crossing Guards; A.M and P.M, Trustee Will Davies, A.M.; Violet Skirten, Supervisor, Crossing Guards, A.M. And P.M.

Observations:

1. The intersection of Wanless Drive and Brisdale Drive is signalized with pedestrian push buttons and enhanced pavement markings. There was a crack in the pavement on the east leg which was a trip hazard. Brisdale Drive has a posted speed limit of 40 km/hr and speed bumps are installed.
 2. During the site inspections, the majority of the pedestrians were adults/secondary school students and there was one family with two elementary students that crossed. One adult rode their bike across the intersection. There were no conflicts between pedestrians and vehicles and there was sufficient time for pedestrians to cross.
 3. Two motorists stopped abruptly on Wanless Drive and reversed.
 4. The intersection of Wanless Drive and Thornbush Boulevard is a signalized intersection with pedestrian push buttons and enhanced pavement markings.
 5. During the site inspections, only a few pedestrians were observed and there was no conflict with vehicles. All pedestrians had sufficient time to cross the roadway.
-

Recommendations:

1. That the site inspection report for St. Aidan Catholic School be received;

2. That the Manager of Road Operations arrange for the crack to be repaired on the east leg of Wanless Drive at Brisdale Drive;

3. That the Crossing Guard Supervisor provide pedestrian safety information to the principal of St. Adian school; and,

4. That the Manager, Transportation Right of Way and Safety arrange for the pedestrian timing to be reviewed prior to September 2025.
