

Date: 2022-06-03

Subject: **Traffic By-law 93-93 – Administrative Update – File I.AC (TRAF)**

Contact: Binita Poudyal, Traffic Operations Technologist, Road Maintenance, Operations and Fleet, Public Works and Engineering Department, 905-874-2878

Report Number: Public Works & Engineering-2022-624

Recommendations:

1. That the report titled: **Traffic By-law 93-93 – Administrative Update – (R624/2022 – File I.AC TRAF)**, to the Committee of Council meeting of June 22, 2022, be received; and,
2. That Traffic By-law 93-93, as amended, be further amended.

Overview:

- **Administrative changes are required to update and/or add new by-law information to the appropriate schedules and consolidated text of the General Traffic By-law 93-93.**
- **The by-law schedule relating to “U-Turns” and “Community Safety Zones” are impacted by this administrative update.**

Background:

Administrative changes to Traffic By-law 93-93 are necessary on a regular basis as staff identifies, adds and modifies by-law information to the appropriate schedules of the by-law. This allows Traffic By-law 93-93 to support appropriate changes to the City’s road network and subsequent traffic and parking regulations.

Current Situation:

The following amendments to the schedule of Traffic By-law 93-93 are recommended:

Brampton School Traffic Safety Council (Schedule II):

The recommendations from the Brampton School Traffic Safety Council have been reviewed by staff and require U-turn restrictions on Howard Stewart Road and Mount Royal Circle in the vicinity of following schools. Changes to the “U-Turns” schedule of Traffic By-law 93-93 will be made accordingly.

- Whaley’s Corners Public School (Ward 6)
- Our Lady-Lourdes Catholic Elementary School (Ward 10)

Community Safety Zones (Schedule XIV):

Based on the report to the July 8, 2020 Council meeting titled “Timetable for Automated Speed Enforcement Implementation”, the following roadway sections are recommended to be designated as Community Safety Zones to meet the provincial requirements for implementing Automated Speed Enforcement.

Street Name	Between	Ward
Churchville Road	Steeles Avenue West and Creditview Road	6
Creditview Road	Steeles Avenue West and Hallstone Road	6

Corporate Implications:

Financial Implications:

There is no financial impact resulting from the recommendations in this report.

Other Implications:

Term of Council Priorities:

This report incorporates the Vision Zero framework into transportation planning, design and operations to prevent fatal and serious injury from motor vehicle collisions within the City right-of-way.

Conclusion:

The aforementioned administrative updates to Traffic By-law 93-93 are required to support appropriate changes to the City's road network and subsequent traffic and parking regulations.

Authored by:

Reviewed by:

Binita Poudyal
Traffic Operations Technologist
Road Maintenance, Operations and
Fleet,
Public Works and Engineering

Tim Kocialek
Director,
Road Maintenance, Operations and Fleet
Public Works and Engineering

Approved by:

Michael Parks, C.E.T., B.A. Leadership
Interim Commissioner
Road Maintenance, Operations and
Fleet
Public Works and Engineering