

Brampton Safety Council Site Inspection Report

Date: OCTOBER 20, 2020 Ward: 6

School/Location: St. Jean-Marie Vianney Catholic School, 75 Jordensen Drive

Principal: Joceline Adusei **Time(s):** 8:30 a.m. and 3:30 p.m.

Phone: 905-890-7610 **Weather:** Slight overcast (a.m.) / Sunny & clear (p.m.)

Requested By: Marrissa Martindale, Brampton resident

Nature of Problem: Crossing Guard inquiry at intersection Williams Parkway & Valleyway Drive

Observers Present: (a.m.) - Renee Crone, member; Max Kazman, member; Margaret Laramore Crossing Guard, Team Lead; (p.m.) Renee Crone, member; Abdul Rashid, member; Margaret Laramore, Crossing Guard, Team Lead


Observations:

- 1. The intersection of Valleyway Drive and Williams Parkway is a signalized intersection, highlighted with clear enhanced pavement markings on all legs of the intersection.
- 2. The following signage is posted on Williams Parkway:
 - Speed limit of 50 km/hr in the vicinity of St. Roch Catholic School
 - "No Stopping" restrictions on the north side on Williams Parkway
 - No "U-Turn" signage on William Parkway
- 3. The following signage is posted on Valleyway Drive:
 - "No Parking" restrictions along the north side leading up to the intersection
 - "Walking Route" and "Watch for Children" signage are in place on the south side
- 4. During the morning observation, four grade 7 boys crossed William Parkway safely without any issues. No students from Junior Kindergarten to grade 5 were observed crossing.
- 5. During the afternoon inspection, three children under grade 5 crossed Williams Parkway. They activated the push button, and had sufficient time to cross without any conflict.

RECOMMENDATIONS

- 1. That the Site Inspection report be received; and
- 2. That a Crossing Guard is not warranted at the intersection of Williams Parkway and Valleyway Drive at this time.

Williams Parkway and Valleyway Drive School Site Inspection October 20, 2020



The intersection of Williams Parkway and Valleyway Drive