## Flower City



## Brampton Safety Council Site Inspection Report

Date: Wednesday, June14/2023 - Ward: 5

School/Location: Springbrook Public School, 145 Jordensen Drive

Principal: Rita Walker Time(s): 8:00 A.M. and 2:50 P.M.

Phone: 905-796-4447 Weather: clear

Requested By: Regional Councilor Paul Vicente

Nature of Problem: Crossing Guard request and traffic congestion at Jordensen Dr. and Lisson Cres.

Observers Present: Charles Gonsalves, Citizen Member (A.M.); Margaret Laramore, Crossing Guard Team Lead (A.M./P.M.); Satvir Dhaliwal, Citizen

Member (P.M.); Carla Green, Citizen Member (P.M.)

## Observations:

- 1. The intersection of Jordensen Drive and Lisson/Hanbury Crescent is located at the rear of Springbrook Public School. The speed limit is posted at 40 km/hr on Jordensen Drive.
- 2. The intersection is an All Way stop and crosswalk lines are painted on all legs of the intersection, however the lines were faded, fitted
- 3. During the site inspection, approximately 100 pedestrians utilized the intersection. There were sufficient gaps in traffic and no conflicts with pedestrians and vehicular traffic were observed.
- 4. During the site inspection there was a little vehicular congestion on Jordensen Drive, but it cleared up quickly.

## Recommendations:

- 1. That the Site Inspection report for Springbrook Public School be received;
- 2. That a crossing guard is not warranted at the intersection of Jordensen Drive and Lisson/Hanbury Crescent; and
- 3. That the Manager of Traffic Operations and Parking be requested to arrange for enhanced crosswalk markings at the intersection of Jordensen Drive and Lisson/Hanbury Crescent.