



SITE INSPECTION FOR LOUGHEED MIDDLE SCHOOL,
INTERSECTION OF FERNFORD DR. AND SANDALWOOD PKWY
THURSDAY, JUNE 22, 2023



AERIAL VIEW OF THE INTERSECTION OF FERNFORD DR AND SANDALWOOD PKWY



AERIAL VIEW OF THE LOUGHEED MIDDLE SCHOOL, THE INTERSECTION OF FERNFORD AND SANDALWOOD AND THE TWO INTERSECTIONS WITH CROSSING GUARDS

SITE INSPECTION FOR LOUGHEED MIDDLE SCHOOL,
INTERSECTION OF FERNFOREST DR. AND SANDALWOOD PKWY
THURSDAY, JUNE 22, 2023



Examples of cracks and holes that are tripping hazards



Asphalt is breaking away from the cables under it



Same as above